

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

300
WNW
1/4-1/2
0.448 mi.
2367 ft.

GORMELY RESIDENCE
158 BAY 54TH ST
BROOKLYN, NY

NY LTANKS **S103038541**
N/A

Relative:
Higher

Actual:
8 ft.

LTANKS:

Name: GORMELY RESIDENCE
Address: 158 BAY 54TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9714165 / 1998-03-20
Facility ID: 9714165
Site ID: 295203
Spill Date: 1998-03-20
Spill Cause: Tank Overfill
Spill Source: Commercial Vehicle
Spill Class: C4
Cleanup Ceased: Not reported
SWIS: 2401
Investigator: KSTANG
Referred To: Not reported
Reported to Dept: 1998-03-21
CID: 370

Water Affected: Not reported
Spill Notifier: Responsible Party
Last Inspection: Not reported
Recommended Penalty: False
Meets Standard: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 1998-03-21
Spill Record Last Update: 1998-03-23
Spiller Name: ABOVE CALLER
Spiller Company: ALMAR FUEL
Spiller Address: 918 MCDONALD AVE
Spiller County: 001
Spiller Contact: MRS GORMELY
Spiller Phone: (718) 449-3837
Spiller Extention: Not reported
DEC Region: 2
DER Facility ID: 238879
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was TANG "

Remarks: "overfill of tank - spill contained and partially cleaned - rest of cleanup in progress"

All Materials:

Site ID: 295203
Operable Unit ID: 1057025
Operable Unit: 01
Material ID: 325134
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10.00
Units: G
Recovered: .00
Oxygenate: Not reported